

TB033 (Rev1) - Isolating Position Problems to Control or Mechanics

Overview

This document describes the techniques to be used when it is necessary to determine whether a position problem lies in the CNC control or whether the problem is caused by machine mechanics.

Tests

The first test is to verify extra or missing encoder counts looking at the absolute position in the PID display. The machine should be powered up and properly homed.

This example will use the X axis and assumes that the machine homes in the X+ direction. It uses the "M92 /X" command to send the table to the "X+" home position. If homing in the "X-" direction the "M91 /X" command would be used.

Steps:

- At the main menu press **ALT+P**, then press **F3 - MDI**. you should see a display similar to the one below.

WCS #1 (G54) Current Position (Inches) Job Name: cc_error.cnc
X +0.0000 Tool: T1 H0
Y +0.0000 Feedrate: 51%
Z +0.0000 Spindle: 0 A

Tool change: T1 1/8 endmill
Operator abort: job cancelled
Stopped
MDI...

Dist to Go
X +0.0000
Y +0.0000
Z +0.0000

Check for encoder movement here for axis in question

Axis	Error	Sum	Delta	PID Out	Abs Pos	Max Error
X*	0	264	0	1	0	1
Y*	1	249	0	1	-1	1
Z	0	260	0	1	0	1
N	0	0	0	OFF	1	0
N*	0	0	0	OFF	0	0

Block?

Rapid Off F9

- In the MDI Block type "**M92 /X**", then press **CYCLE START**. The X axis will move to the plus home switch.
NOTE: This is a slow move and you may want to jog the axis closer to the home position before pressing **CYCLE START**.
- When the axis stops moving check the "Abs Pos" for the axis under test, it should read zero.
- If the "Abs Pos" is zero, then the mispositioning most likely is the result of fixture or part movement while being cut.
- If the "Abs Pos" is **NOT** zero then proceed to the next test.

The next test for isolating a position problem is basically to remove the control (the motor) from the ballscrew,

