

# TB176 (Rev1) - Missing midas.dll File

---

## Overview


This document describes how to add the midas.dll file to the registry.

## Procedure


1) Bring up the start menu and click on run.



2) Type in ?regsvr32.exe c:\cnc10\midas.dll?. This will work for the mill offline intercon.



3) You should get a box that pops up and says DllRegisterServer in c:\cnc10\midas.dll succeeded. Click OK



## Other Centroid Offline Software

In the example above, we fixed Mill Intercon Offline. For other software programs you will do the same, but change the directory. Below is a list of examples of what you would type in the run screen.

- \* Lathe Intercon Offline - regsvr32.exe c:\cnc10\midas.dll
- \* Mill Demo Software - regsvr32.exe c:\milledemo\midas.dll
- \* Lathe Demo Software - regsvr32.exe c:\lathdemo\midas.dll

---

## Document History

